



Lead Service Line Inventory

*Please enter informal *Please enter totals	Water System Name		Mount Zion		System ID Number:		IL1150350		Current Inventory Date:		4/10/2024				
	Total Service Lines:		2228		Total Lead:		0		Total Galvanized Requiring replacement:		0		Total Unknown:		
												Website link to Material Inventory:		<a href="https://www.mtzion.com/water-quality-report">https://www.mtzion.com/water-quality-report</a>	

Service Address	Lead and Copper Sample site number	Is this a high-risk facility or Area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/ Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line Material	Was Galvanized Service Line Material ever downstream of Lead?	Date Customer Notified of Lead Service Line	Was a Lead Service Line Previously RePld at this Location?	Date Lead Service Line RePld	Material of Service Line RePlment	Has the customer refused access to the property?	Date of customer waiver or IDPH notification, if customer refused access to property
		EXAMPLES: Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities	Yes (Y) or No (N)	What year was the PWS-Owned Service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? EXAMPLES: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, Unknown (U) Unknown Not Lead (UNL)	EXAMPLES: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring RePlment (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	EXAMPLES: Copper - Lead Solder (CLS) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring RePlment (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	EXAMPLES: Lead (L) Galvanized Requiring Replacement (GRR) Non-Lead (NL)	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N).  If Yes, that section of service line should be marked as Galvanized Requiring RePlment in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was rePld. / Leave blank if previous column was (N).	EXAMPLES: Copper - No Lead Solder (C) Galvanized (G) Plastic - PVC, HDPE, PEX (P) Cast/Ductile Iron or Transite (O) Leave blank if no Lead Service Line was rePld.	Yes (Y) or No (N)	If customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver / Leave blank if customer has not refused access
1440 Alexander Dr	N/A	N	N	1991	2001	Visual Inspections	C	C	C	NL	N	N/R	N				
1460 Alexander Dr	N/A	N	N	1991	1992	Visual Inspections	C	C	C	NL	N	N/R	N				
1465 Alexander Dr	N/A	N	N	1991	1997	Visual Inspections	C	C	C	NL	N	N/R	N				
1480 Alexander Dr	N/A	N	N	1991	1991	Visual Inspections	C	C	C	NL	N	N/R	N				
1510 Alexander Dr	N/A	N	N	1991	1994	Visual Inspections	C	C	C	NL	N	N/R	N				
1515 Alexander Dr	N/A	N	N	1991	1991	Visual Inspections	C	C	C	NL	N	N/R	N				
1520 Alexander Dr	N/A	N	N	1991	1996	Visual Inspections	C	C	C	NL	N	N/R	N				
1530 Alexander Dr	N/A	N	N	1991	2003	Visual Inspections	C	C	C	NL	N	N/R	N				
1530 Alexander Dr 2nd Meter	N/A	N	N	1991	2003	Visual Inspections	C	C	C	NL	N	N/R	N				
1540 Alexander Dr	N/A	N	N	1991	2003	Visual Inspections	C	C	C	NL	N	N/R	N				
1545 Alexander Dr	N/A	N	N	1991	1991	Visual Inspections	C	C	C	NL	N	N/R	N				
1565 Alexander Dr	N/A	N	N	1991	1993	Visual Inspections	C	C	C	NL	N	N/R	N				
1585 Alexander Dr	N/A	N	N	1991	2001	Visual Inspections	C	C	C	NL	N	N/R	N				
1585 Alexander Dr 2nd Meter	N/A	N	N	1991	2001	Visual Inspections	C	C	C	NL	N	N/R	N				
1610 Alexander Dr	N/A	N	N	1991	1990	Visual Inspections	C	C	C	NL	N	N/R	N				
1615 Alexander Dr	N/A	N	N	1991	1992	Visual Inspections	C	C	C	NL	N	N/R	N				
10 Alexander Ct	N/A	N	N	1991	1991	Visual Inspections	C	C	C	NL	N	N/R	N				
11 Alexander Ct	N/A	N	N	1991	1991	Visual Inspections	C	C	C	NL	N	N/R	N				
12 Alexander Ct	N/A	N	N	1991	1990	Visual Inspections	C	C	C	NL	N	N/R	N				
8 Alexander Ct	N/A	N	N	1991	1992	Visual Inspections	C	C	C	NL	N	N/R	N				
8 Alexander Ct 2nd Meter	N/A	N	N	1991	1992	Visual Inspections	C	C	C	NL	N	N/R	N				
9 Alexander Ct	N/A	N	N	1991	1993	Visual Inspections	C	C	C	NL	N	N/R	N				
9 Alexander Ct 2nd Meter	N/A	N	N	1991	1993	Visual Inspections	C	C	C	NL	N	N/R	N				
945 S Antler Dr	N/A	N	N	1973	1978	Visual Inspections	C	C	C	NL	N	N/R	N				
554 N Antler Dr	N/A	N	N	1971	1976	Visual Inspections	C	C	C	NL	N	N/R	N				
550 S Antler Dr	N/A	N	N	1975	1976	Visual Inspections	C	C	C	NL	N	N/R	N				
555 S Antler Dr	N/A	N	N	1975	1977	Visual Inspections	C	C	C	NL	N	N/R	N				
560 S Antler Dr	N/A	N	N	1975	1976	Visual Inspections	C	C	C	NL	N	N/R	N				
564 N Antler Dr	N/A	N	N	1977	1978	Visual Inspections	C	C	C	NL	N	N/R	N				
574 N Antler Dr	N/A	N	N	1977	1978	Visual Inspections	C	C	C	NL	N	N/R	N				
584 N Antler Dr	N/A	N	N	1977	1978	Visual Inspections	C	C	C	NL	N	N/R	N				
600 S Antler Dr	N/A	N	N	1975	1976	Visual Inspections	C	C	C	NL	N	N/R	N				
604 N Antler Dr	N/A	N	N	1977	1978	Visual Inspections	C	C	C	NL	N	N/R	N				
605 S Antler Dr	N/A	N	N	1975	1977	Visual Inspections	C	C	C	NL	N	N/R	N				
610 S Antler Dr	N/A	N	N	1975	1976	Visual Inspections	C	C	C	NL	N	N/R	N				
614 N Antler Dr	N/A	N	N	1977	1978	Visual Inspections	C	C	C	NL	N	N/R	N				
615 S Antler Dr	N/A	N	N	1975	1975	Visual Inspections	C	C	C	NL	N	N/R	N				
620 S Antler Dr	N/A	N	N	1975	1976	Visual Inspections	C	C	C	NL	N	N/R	N				
623 N Antler Dr	N/A	N	N	1977	1987	Visual Inspections	C	C	C	NL	N	N/R	N				
625 S Antler Dr	N/A	N	N	1975	1976	Visual Inspections	C	C	C	NL	N	N/R	N				
630 S Antler Dr	N/A	N	N	1975	1976	Visual Inspections	C	C	C	NL	N	N/R	N				
633 N Antler Dr	N/A	N	N	1977	1987	Visual Inspections	C	C	C	NL	N	N/R	N				
634 N Antler Dr	N/A	N	N	1977	1978	Visual Inspections	C	C	C	NL	N	N/R	N				
635 S Antler Dr	N/A	N	N	1975	1976	Visual Inspections	C	C	C	NL	N	N/R	N				
640 S Antler Dr	N/A	N	N	1975	1976	Visual Inspections	C	C	C	NL	N	N/R	N				
643 N Antler Dr	N/A	N	N	1977	1978	Visual Inspections	C	C	C	NL	N	N/R	N				
644 N Antler Dr	TP1A006	N	N	1977	1984	Visual Inspections	C	C	C	NL	N	N/R	N				
645 S Antler Dr	N/A	N	N	1975	1976	Visual Inspections	C	C	C	NL	N	N/R	N				
650 S Antler Dr	N/A	N	N	1975	1976	Visual Inspections	C	C	C	NL	N	N/R	N				
653 N Antler Dr	N/A	N	N	1977	1978	Visual Inspections	C	C	C	NL	N	N/R	N				
654 N Antler Dr	TP1A001	N	N	1977	1983	Visual Inspections	C	C	C	NL	N	N/R	N				
655 S Antler Dr	N/A	N	N	1975	1975	Visual Inspections	C	C	C	NL	N	N/R	N				
660 S Antler Dr	N/A	N	N	1975	1975	Visual Inspections	C	C	C	NL	N	N/R	N				
663 N Antler Dr	TP1A002	N	N	1977	1978	Visual Inspections	C	C	C	NL	N	N/R	N				
664 N Antler Dr	N/A	N	N	1977	1984	Visual Inspections	C	C	C	NL	N	N/R	N				
665 S Antler Dr	N/A	N	N	1975	1975	Visual Inspections	C	C	C	NL	N	N/R	N				
673 N Antler Dr	N/A	N	N	1977	1978	Visual Inspections	C	C	C	NL	N	N/R	N				
674 N Antler Dr	N/A	N	N	1977	1986	Visual Inspections	C	C	C	NL	N	N/R	N				
683 N Antler Dr	N/A	N	N	1977	1986	Visual Inspections	C	C	C	NL	N	N/R	N				
700 S Antler Dr	N/A	N	N	1975	1977	Visual Inspections	C	C	C	NL	N	N/R	N				
704 N Antler Dr	TP1A003	N	N	1977	1984	Visual Inspections	C	C	C	NL	N	N/R	N				
705 S Antler Dr	N/A	N	N	1975	1976	Visual Inspections	C	C	C	NL	N	N/R	N				
710 S Antler Dr	N/A	N	N	1975	1977	Visual Inspections	C	C	C	NL	N	N/R	N				
713 N Antler Dr	N/A	N	N	1977	1978	Visual Inspections	C	C	C	NL	N	N/R	N				
715 S Antler Dr	N/A	N	N	1975	1976	Visual Inspections	C	C	C	NL	N	N/R	N				
720 S Antler Dr	N/A	N	N	1975	1977	Visual Inspections	C	C	C	NL	N	N/R	N				
723 N Antler Dr	N/A	N	N	1975	1986	Visual Inspections	C	C	C	NL	N	N/R	N				
724 N Antler Dr	N/A	N	N	1977	1984	Visual Inspections	C	C	C	NL	N	N/R	N				
725 S Antler Dr	N/A	N	N	1975	1976	Visual Inspections	C	C	C	NL	N	N/R	N				
730 S Antler Dr	N/A	N	N	1975	1975	Visual Inspections	C	C	C	NL	N	N/R	N				









































